

## Test Report

No. CANMLC2304532901

Date: 04 Apr 2023

Page 1 of 3

Client Name : SHANGHAI INTCO INDUSTRIES CO., LTD

Client Address : NO.1299 HUBIN ROAD,HUQIAO TOWN, FENG XIAN DISTRICT, SHANGHAI 201417 P. R. CHINA

Sample Name : Acoustic wall panel

Manufacturer : Shandong INTCO Recycling Resources Co., Ltd.

The above sample(s) and information were provided by the client.

SGS Job No. : GZIN2303000654CM - GZ

SGS Ref No. : SHIN2303000487CM;IN-SH-CP-5627-23058

Date of Sample Received : 28 Mar 2023

Testing Period : 28 Mar 2023 - 03 Apr 2023

Test Requested : Selected test(s) as requested by the client.

Test Method(s) : Please refer to next page(s).

Test Result(s) : Please refer to next page(s).

Signed for and on behalf of  
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Jessie Li

Jessie Li  
Approved Signatory

scan to see the report



CANMLC2304532901



SGS-CSTC Standards Technical Services Co., Ltd.  
Guangzhou Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at <https://www.sgs.com/en/Terms-and-Conditions>. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.  
**Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: [CN.Doccheck@sgs.com](mailto:CN.Doccheck@sgs.com)**

No.198, Kezhu Road, Science City, Economic & Technological Development Area, Guangzhou, Guangdong, China 510663  
中国·广东·广州高新技术产业开发区科学城科珠路198号 邮编: 510663

t (86-20) 82155555 www.sgs.com  
t (86-20) 82155555 sgs.china@sgs.com

## Test Report

No. CANMLC2304532901

Date: 04 Apr 2023

Page 2 of 3

Test Result(s) :

### Test Part Description :

Specimen No.	SGS Sample ID	Description
SN1	CAN23-045329.001	Brown wood strip

Remarks :

- (1) 1 mg/kg = 1 ppm = 0.0001%
- (2) MDL = Method Detection Limit
- (3) ND = Not Detected ( < MDL )
- (4) "-" = Not Regulated

### Migration of heavy metals

Test Method : With reference to BS EN 12149:1998, analysis was performed by ICP-OES.

Test Item(s)	Unit	MDL	001
Soluble Lead (Pb)	mg/kg	5	ND
Soluble Antimony (Sb)	mg/kg	5	ND
Soluble Arsenic (As)	mg/kg	5	ND
Soluble Barium (Ba)	mg/kg	10	ND
Soluble Cadmium (Cd)	mg/kg	5	ND
Soluble Chromium (Cr)	mg/kg	5	ND
Soluble Mercury (Hg)	mg/kg	5	ND
Soluble Selenium (Se)	mg/kg	10	ND

Notes :

The limit of BS EN 12149-1998 follow to BS EN 15102-2007 Decorative wallcoverings—Roll and panel form products.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (  $w=0$  ) stated in ILAC-G8:09/2019.



Sample photo:



SGS authenticate the photo on original report only

\*\*\* End of Report \*\*\*

